

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	37	(lens adj3 barrel) and (screw same washer) and coupling	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:02
2	BRS	L7	0	((screw\$ same washer\$) same (reinforce\$ near3 plate)) and lens and barrel	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:04
3	BRS	L13	33	((screw same washer) same (reinforce\$ near3 plate))	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 09:58
4	BRS	L19	43	(lens near5 barrel) and (screw same washer) and coupling	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:11
5	BRS	L25	443	(screw\$ same washer\$) same reinforce\$	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:19
6	BRS	L31	0	19 and 25	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:10

	Comments	Error Definition	Errors
1			0
2		Truncation Overflow. Return string from Server is: 5`0`0`SCR	1
3			0
4			0
5		Truncation Overflow. Return string from Server is: 5`0`0`SCR	1
6			0

	Type	L #	Hits	Search Text	DBs	Time Stamp
7	BRS	L37	4	19 and reinforc\$	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:11
8	BRS	L43	5	(lens near5 barrel) and (screw same washer) and reinforc\$	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:21
9	BRS	L49	0	25 and (lens near5 barrel)	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:20
10	BRS	L55	140	(lens near5 barrel) and (screw same washer)	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:22

	Comments	Error Definition	Errors
7			0
8			0
9			0
10			0